## -3,200 sq.ft. Automotive Detail Shop, San Francisco, April 2015-

Old substrate with multiple repairs made over the years



Continuous exposure to water & detergents



Areas shown with standing water




Lots of exposed aggregate, saturated with moisture



Wall coating is peeling off and algae grows on bottom



Whole area diamond grinded & repairs made




CA License # 980836 Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited Office: (888) 887-0483


Castro Valley CA 94546 Email: Info@ImpactFloorSolutions.com

## -3,200 sq.ft. Automotive Detail Shop, San Francisco, April 2015-


Wall has been grinded and filled with resinuous patch




Created coarse profile and dust-free for excellent bonding



1/8" Cementitious urethane floor 'Gem Grey', medium non-skid Chemical, abrasion & impact resistant semi-gloss topcoat




Moisture vapor tolerant system on floor, smooth on wall





Started Monday pm, completed Thursday pm



CA License # 980836 Mobile: (510) 690-7015 Insured, Bonded & BBB Accredited
Office: (888) 887-0483

Castro Valley CA 94546 Email: Info@ImpactFloorSolutions.com