

Impact Floor Solutions, Inc. -Citizen Center Concord May 2013-

Moisture & improper installation caused dis-bonding



Several areas showed complete floor system 'bulging'



Repair area has been marked, edges diamond cut, failing system removed. Ready for surface preparation.



Urecon system installed with non-skid aggregate



Done

