

-Mariposa Baking Company, Oakland, March 2017-

Bare concrete substrate where all epoxy has come off over time



Slippery and hard to clean exposed concrete; a sanitary nightmare



All equipment is being removed & dust barrier installed by client



Almost done with clearing area



Adhesive backed cove strip has got to go as well



All hands on deck with removal, cleanup & preparation for new floor



- Impact Floor Solutions, Inc.-

dba Polymer Floor & Wall Coating Systems

CA License # 980836

Insured, Bonded & BBB Accredited

Castro Valley CA 94546

Mobile: (510) 690-7015

Office: (888) 887-0483

Email: Info@ImpactFloorSolutions.com

-Mariposa Baking Company, Oakland, March 2017-

First step is cleaning & scrubbing with Rock-Tred Microbial cleaner



Vacuum and removal of Microbial cleaner



First pass of aggressive grinding with #30 grit diamonds



Lots of material removed & coarse profiling for superior bonding



Detail grinding around drains & floor sinks



Base coat of cementitious urethane installed; remove excess sand



- Impact Floor Solutions, Inc.-

dba Polymer Floor & Wall Coating Systems

CA License # 980836
Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited
Office: (888) 887-0483

Castro Valley CA 94546
Email: Info@ImpactFloorSolutions.com

-Mariposa Baking Company, Oakland, March 2017-

Application of topcoat with notched squeegee & back roll



Three part cementitious urethane in light grey will last a long time



Saturday morning baking company in production



Next Thursday night area transformed & back in business



All cracks & imperfections filled & prepared prior to topcoat



Longest lasting floor system w/ light non-skid texture & easy to clean



- Impact Floor Solutions, Inc. -
dba Polymer Floor & Wall Coating Systems

CA License # 980836
Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited
Office: (888) 887-0483

Castro Valley CA 94546
Email: Info@ImpactFloorSolutions.com