

-Martinez Juvenile Hall, August 2013-

Existing coating had too much sand and was completely deteriorated & saturated. Removal with chipping hammer of all 6 shower stalls



Plumbing fixtures leaks & saturation made for additional challenges



After repairs & drying substrate a 3-part cementitious urethane coat



Recoat whole area to properly seal with off-white chemical resistant topcoat & medium non-skid texture



- Impact Floor Solutions, Inc.-
Polymer Floor & Wall Coating Systems

CA License # 980836
Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited
Office: (888) 887-0483

Castro Valley CA 94546
Email: Info@ImpactFloorSolutions.com