

# -The Ritz-Carlton (Employee Showers), March 2017-

Existing epoxy Quartz floor hard to keep clean; too rough texture.



Area vacuumed, screened & sanded. First recoat preparation step



Dry blow substrate after thorough scrubbing with Rock-Solv cleaner



Wiped down with solvent & install masking tape on outer perimeter



Thick coat of medium viscosity 100% solids epoxy, color Twilight Blue



Anti-bacterial coating with much smoother surface for easy cleaning



**- Impact Floor Solutions, Inc.-**  
dba Polymer Floor & Wall Coating Systems

CA License # 980836  
Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited  
Office: (888) 887-0483

Castro Valley CA 94546  
Email: [Info@ImpactFloorSolutions.com](mailto:Info@ImpactFloorSolutions.com)

# -The Ritz-Carlton (Employee Showers), March 2017-

Before



After



Integrate rubber beads for anti-slip while comfortable for bare feet.

Area blocked allowing for thorough cure prior to back in service



**- Impact Floor Solutions, Inc.-**  
dba Polymer Floor & Wall Coating Systems

CA License # 980836  
Mobile: (510) 690-7015

Insured, Bonded & BBB Accredited  
Office: (888) 887-0483

Castro Valley CA 94546  
Email: [Info@ImpactFloorSolutions.com](mailto:Info@ImpactFloorSolutions.com)