

# -San Mateo County Fleet Garage, June 2016-

Main garage of 7,500 sq.ft. needs floor redone



Large areas of deeply damaged concrete, contaminated with oils



Area grinded, shot blasted and 3/16" urethane slurry installed



Chemical & abrasion resistant topcoat of moisture tolerant floor



Line striping in safety yellow and floor back in service



This fleet maintenance garage has a floor that will last a long time



**Impact Floor Solutions, Inc.**

dba Polymer Floor & Wall Coating Systems  
**Commercial Concrete Coatings & Polishing**

CA License # 980836

(888) 887-0483 [ImpactFloorSolutions.com](http://ImpactFloorSolutions.com)



ACCREDITED  
BUSINESS

A+