

# Impact Floor Solutions, Inc. -Project Trinity Lutheran Church Jan. 2014-

Before



During first pass of grinding



Diamond grinding with 16-grit double segment



Excessive moisture vapor transmission through cracks



Application of densifier/moisture mitigation system



Base coat of Terra Cotta after cementitious overlay



# Impact Floor Solutions, Inc. -Project Trinity Lutheran Church Jan. 2014-

---

Walnut stain



Project finished with sealer

