

-Apartment Complex Lobby, Walnut Creek, September 2014

Old substrate with cracks and divots that fill with dirt



Excessive substrate movement causes low spots



Whole area diamond grinded, cracks opened & patched



Scraping of vinyl flakes to remove sharp edges



Close up of Camouflage Hybrid Flakes, nice & smooth



Water clear topcoat with full gloss when just installed



Impact Floor Solutions, Inc.

dba Polymer Floor & Wall Coating Systems
Commercial Concrete Coatings & Polishing

CA License # 980836

(888) 887-0483 ImpactFloorSolutions.com

