

Worn out epoxy with pinhole cavities & rough texture



Exposed aggregate, makes it hard to clean & porous



Whole area degreased, vacuumed, ready for Microbial Cleaner



After cleaning, we sand screened area twice, ready for primer



New cove base installed, primed, patched & top coated



BASF Orange Peel textured topcoat for superior cleaning capabilities while maintaining non-skid characteristics



- Impact Floor Solutions, Inc.-

dba Polymer Floor & Wall Coating Systems

CA License # 980836

Insured, Bonded & BBB Accredited

Castro Valley CA 94546

Mobile: (510) 690-7015

Office: (888) 887-0483

Email: Info@ImpactFloorSolutions.com