

Impact Floor Solutions, Inc. -Project Henkel Corporation, November 2013-

Before



After removal old coating, profiling and crack repair



Sand screening with 80-grit after priming & more patching



Ready for top coat



Application of top coat by squeegee & back-rolling



Completed

