

# -Showroom concrete polishing 'Hertz Equipment Rental', Oakland, August 2015-

Vinyl composite tile removed, found original terrazzo covered with multiple layers of glue, mastic & sealers



Some areas had 1/4" thick glue that had to be removed



First passes with more aggressive 50-grit metal diamonds



Restrooms also showed terrazzo when overlays removed



After 7 passes grinding & densifying, before final polish



## - Impact Floor Solutions, Inc.-

Polymer Floor & Wall Coating Systems

CA License # 980836

Insured, Bonded & BBB Accredited

Castro Valley CA 94546

Mobile: (510) 690-7015

Office: (888) 887-0483

Email: [Info@ImpactFloorSolutions.com](mailto:Info@ImpactFloorSolutions.com)

# -Showroom concrete polishing 'Hertz Equipment Rental', Oakland, August 2015-

Preparation for densifying to increase substrate strength



Another pass of 400 grit resin pads, already starts to shine



After 12 passes, 9 different grinding pads



Very cool logo that was hidden, came back to life



Restroom alley after glue removal



Completed with 1200 grit finish, all polished & easy to clean



## - Impact Floor Solutions, Inc. -

Polymer Floor & Wall Coating Systems

CA License # 980836

Insured, Bonded & BBB Accredited

Castro Valley CA 94546

Mobile: (510) 690-7015

Office: (888) 887-0483

Email: [Info@ImpactFloorSolutions.com](mailto:Info@ImpactFloorSolutions.com)