

# -Laundromat, Los Angeles, September 2012-

All tile at entryway to be removed prior to concrete profiling



Dirty substrate with lots of imperfections



Divots & spalls opened, cleaned & filled non-shrinking patch material



Fresh patch before smoothing and colorant to be added



Multiple applications of Walnut stain penetrates deep in concrete.



Finished with water-clear epoxy sealer and non-slip aggregate



- Impact Floor Solutions, Inc.-

dba Polymer Floor & Wall Coating Systems

CA License # 980836

Insured, Bonded & BBB Accredited

Castro Valley CA 94546

Mobile: (510) 690-7015

Office: (888) 887-0483

Email: [Info@ImpactFloorSolutions.com](mailto:Info@ImpactFloorSolutions.com)