Impact Floor Solutions, Inc. -Solano County Jail, March 2014-

Before, delaminating rubber mats over saturated concrete



Multiple overlays & improper surface preparation



1/4" trowel down urethane slurry with epoxy seal coat



Adhesive looses bond because of moisture & food grease



Removed all overlays, glues & cleaned with microbial

